



**STATEMENT SHOWING THE ACTION TAKEN REPORT BY THE HMWS&SB AGAINST THE "UN WHOLESOME"
SAMPLES REPORTED BY I.P.M DURING THE MONTH OF APRIL-2014**


SL. No.	I.P.M Lab Ref. No.	Location	O&M Div. No.	Section	Action taken Report by Concerned Manager (Engg.) Rectified / Work in progress	Resampling by QAT of HMWSSB					Satisfactory / Unsatisfactory
						RC	H2S	Date	Lab Ref. No.	Bacteriological Analysis	
1.	1003	PSP at outside at Aliabad Reservoir	II	Aliyabad	Rectified	1.0	--	17-05-2014	5383	Wholesome	Satisfactory
2.	1012	PSP outlet at Chilkalguda S/R	V	Chilkalguda	Rectified	1.0	--	17-04-2014	1689	Wholesome	Satisfactory
3.	1033	Tap inside outlet at Tarnaka Reservoir	VII	Tarnaka	Rectified	2.0	--	22-05-2014	2341	Wholesome	Satisfactory
4.	1037	Outlet tap at Navodaya Nagar	III	Mehdipatnam	Rectified	1.0	--	16-05-2014	1920	Wholesome	Satisfactory
5.	1041	Outlet tap at HB Colony Section phase -II	IX	KPHB	Rectified	0.5	--	02-06-2014	2632	Wholesome	Satisfactory
6.	1067	Direct from com-I Prashasan Nagar S/R	VI	Jubilee Hills	Rectified	1.5	--	23-05-2014	2225	Wholesome	Satisfactory
7.	1080	PSP Outside at Tarnaka Section Reservoir	VII	Tarnaka	Rectified	0.2	--	13-05-2014	1181	Unwholesome	Un satisfactory
8.	1081	House tap pit at 12-1-1119/26/A, Indiranagar Northlaguda, Sec-bad	VII	Tarnaka		Online Supply, Starting initial pollution was observed.					
9.	1083	Direct from comp No; I (GLSR) Vasavinagar S/R	X	Vasavi nagar	Rectified	2.0	--	19-05-014	2064	Wholesome	Satisfactory
10.	1092	Dirctet from sump water at NTR nagar S/R	X	Alikapuri	Rectified	2.0	--	19-05-2014	2065	Wholesome	Satisfactory
11.	1100	PSP at 12-2-683 /A/2 Gudimalkapur Slum	III	Mehdipatnam	Rectified	0.5	--	16-05-2014	1921	Wholesome	Satisfactory
12.	1108	PSP near Tanker Filling Point at Gouse Nagar , Bandlaguda	II	Bandlaguda	Rectified	0.5	--	31-05-2014	5646	Wholesome	Satisfactory

SL. No.	I.P.M Lab Ref. No.	Location	O&M Div. No.	Section	Action taken Report by Concerned Manager (Engg.) Rectified / Work in progress	Resampling by QAT of HMWSSB					Satisfactory / Unsatisfactory
						RC	H2S	Date	Lab Ref. No.	Bacteriological Analysis	
13.	1125	House tap at plot No: 426 Shathavahana Nagar, Bhagya Nagar Colony, KPHB	IX	KPHB	Rectified	0.5	--	17-05-2014	1924	Unwholesome	Unsatisfactory
14.	1127	House tap pit MIG -II plot No: 141, IX th Phase Bhagya Nagar Colony, KPHB	IX	KPHB	Rectified	0.5	--	13-05-2014	1766	Wholesome	Satisfactory
15.	1128	Tanker Filling Point at IV th Phase Bhagya Nagar Colony, KPHB	IX	KPHB	Rectified	0.5	--	20-05-2014	2085	Unwholesome	Unsatisfactory
16.	1191	House tap 1-6-67 at Gandhi Girijan, Habsiguda colony	XIII	Habsiguda	Rectified	1.0	--	26-05-2014	2358	Wholesome	Satisfactory
17.	1196	House tap 20-9/21 at Chilkkanagar, Uppal	XIV	Uppal	Rectified	0.1	--	26-05-2014	2356	Wholesome	Satisfactory
18.	1209	House tap pit 3-5-948/53 Gandhi Kuteer slum, Narayanaguda	V	Narayanguda	Rectified	0.5	--	23-05-2014	2369	Wholesome	Satisfactory
19.	1217	Tanker Filling Point -3 at Erragadda S/R	VI	Erragadda	Rectified	0.2	--	11-05-2014	1693	Wholesome	Satisfactory
20.	1220	PSP beside D.No: 20-2-531/1 Hussaini Alam	I	DOodh bowli	Rectified	1.0	--	23-05-2014	5490	Wholesome	Satisfactory
21.	1237	House tap opp 2-2-1107/15/B Bhavani Temple lane Rly bridge Nallakunta	V	Adikmet	Rectified	0.5	--	22-05-2014	2346	Unwholesome	Unsatisfactory
22.	1239	House tap pit at street No; 2 GHMC 170 Narasimha Basti, Nallakunta	V	Adikmet	Rectified	0.5	--	26-05-2014	2425	Wholesome	Satisfactory
23.	1241	House Tap pit 2-3-42/C/49 Quadri Bagh Amberpet	V	Shivam	Rectified	0.5	--	16-05-2014	2240	Wholesome	Satisfactory

SL. No.	I.P.M Lab Ref. No.	Location	O&M Div. No.	Section	Action taken Report by Concerned Manager (Engg.) Rectified / Work in progress	Resampling by QAT of HMWSSB					Satisfactory / Unsatisfactory
						RC	H2S	Date	Lab Ref. No.	Bacteriological Analysis	
24.	1255	Outlet tap at Balanagar S/R Kukatpally	IX	Balanagar	Rectified	0.5	--	26-05-2014	2338	Wholesome	Satisfactory
25.	1273	PSP near H.No: 4-33-10/2 Venkataswara Nagar road Jagadgirigutta	XII	Shapoomnagar	Rectified	0.5	--	02-06-2014	2628	Wholesome	Satisfactory
MARCH 2014 (PENDING)											
1.	811	PSP beside at 13-3-10/5 Mustaidpura kaman road	IV	Jiyaguda	Rectified	1.0	--	22-05-2014	2215	Wholesome	Satisfactory


Technical Officer (QAT)
 Bacteriological Section
 Central Laboratory.


Dy. General Manager (QAT)
 Quality Assurance & Testing Wing,
 HMWS&SB, Hyderabad


General Manager (QAT) I/C
 Quality Assurance & Testing Wing,
 HMWS&SB, Hyderabad

1. Copy submitted to the Managing Director, HMWS&SB for favour of information
2. Copy submitted to the Director (Technical), HMWS&SB for favour of information.
- ✓ 3. Copy submitted to the Chief Water Analyst, I.P. M, Narayanguda for favour of information