




**STATEMENT SHOWING THE ACTION TAKEN REPORT BY THE HMWS&SB AGAINST THE "UN WHOLESOME"
SAMPLES REPORTED BY I.P.M DURING THE MONTH OF FEBRUARY-2014**

SL. No.	I.P.M Lab Ref. No.	Location	O&M Div. No.	Section	Action taken Report by Concerned Manager (Engg.) Rectified / Work in progress	Resampling by QAT of HMWSSB					Satisfactory Unsatisfactory
						RC	H2S	Date	Lab Ref. No.	Bacteriological Analysis	
1.	382	House Tap at H.No: 5-7-1/99 Hariharapuram, Vanasthalipuram	X	Vanasthalipuram	Rectified	0.2	--	25-03-2014	24335	Wholesome	Satisfactory
2.	416	Tanker Filling Point at Jiyaguda S/R	IV	Ziaguda	Rectified	1.0	--	15-03-2014	23836	Wholesome	Satisfactory
3.	418	PSP Outside at Bogullakunta S/R	IV	Hindi nagar	Rectified	1.5	--	12-03-2014	23643	Wholesome	Satisfactory
4.	433	Tap inside at Erragadda Section	VI	Erragadda	Rectified	1.5	--	22-03-2014	24157	Wholesome	Satisfactory
5.	455	PSP at Bandlaguda S/R	II	Santosh nagar	Rectified	1.0	--	21-03-2014	MRG 4360	Wholesome	Satisfactory
6.	459	House Tap at H.No; 8-5-4/12/5, Durganagar, Mailardevpally	XVI	Mailardevpally	Rectified	1.5	--	11-03-2014	23597	Wholesome	Satisfactory
7.	468	House tap pit at 6-1-361/104, Gandhi Nagar, Khairatabad	IV	Red Hills High Level	Rectified	2.0	--	13-03-2014	23748	Wholesome	Satisfactory
8.	528	House tap at H.No: 16-9-583/5/A, old Malakpet	II	Malakpet	Rectified	1.0	--	14-03-2014	23789	Wholesome	Satisfactory
9.	530	PSP Outlet at Santoshnagar Section Reservoir	II	SANTOSH nagar	Rectified	1.0	--	20-03-2014	MRG 4326	Wholesome	Satisfactory

SL. No.	I.P.M Lab Ref. No.	Location	O&M Div. No.	Section	Action taken Report by Concerned Manager (Engg.) Rectified / Work in progress	Resampling by QAT of HMWSSB					Satisfactory / Unsatisfactory
						RC	H2S	Date	Lab Ref. No.	Bacteriological Analysis	
10.	568	Tap inside at Rudranagar	Contonment Board		Rectified	1.0	--	25-03-2014	24305	Wholesome	Satisfactory
11.	586	Stored water (21-02/14) D.No: 1-9-67 Rajendernagar main road	XVI	Budvel	Rectified	1.5	--	15-03-2014	23806	Wholesome	Satisfactory
12.	628	House Tap pit at LIGH KPHB Quarter No: 157/1, IV th Phase KPHB	IX	KPHB	Rectified	0.5	--	19-03-2014	23980	Wholesome	Satisfactory
13	629	House tap pit LIGH KPHB Quarter No: 117/ 11 IV th Phase KPHB Colony	IX	KPHB	Rectified	0.5	--	19-03-2014	23979	Wholesome	Satisfactory


Technical Officer (QAT)
 Bacteriological Section
 Central Laboratory.


Dy. General Manager (QAT)
 Quality Assurance & Testing Wing,
 HMWS&SB, Hyderabad


General Manager (QAT) I/C
 Quality Assurance & Testing Wing,
 HMWS&SB, Hyderabad

1. Copy submitted to the Managing Director, HMWS&SB for favour of information
2. Copy submitted to the Director (Technical), HMWS&SB for favour of information.
3. Copy submitted to the Chief Water Analyst, I.P. M, Narayanguda for favour of information