

| | | | | | | | | | | | | | | |
|----|---------|-----|---|----------------------------------------------------------------------|-----|------|--------|-----------------|-------|-------|-------|-------|-------|---------------------------|
| | | | | thoata | | | | | | | | | | |
| 16 | „ | 492 | „ | Tap at D.No: 12-28-54, Sd.Agraharam | 0.5 | Nil | - | Satisfactory | | | | | | |
| 17 | „ | 494 | „ | Tap at D.No: 13-2-18, Gunturu vari thoata | 0.2 | Nil | -- | Satisfactory | | | | | | |
| 18 | „ | 496 | „ | D.No:L 14-2-83, Pothuru vari thoata | 0.5 | Nil | -- | Satisfactory | | | | | | |
| 19 | „ | 498 | „ | Tap at Sarada colony SR | 1.5 | Nil | -- | Satisfactory | | | | | | |
| 20 | „ | 500 | „ | PT Velangini nagar library | 1.0 | Nil | -- | Satisfactory | | | | | | |
| 21 | 17.5.14 | 540 | „ | PWS Scheme, Narasaraopet Municipality Tap at Palapadu road SR | 2.0 | Nil | - | Satisfactory | | | | | | |
| 22 | 21.5.14 | 554 | „ | PWS Scheme, Guntur MPL, Corpn., Tap at PH office SR | 1.0 | Nil | - | Satisfactory | | | | | | |
| 23 | „ | 556 | „ | Tap at Nallacheruvu SR | 2.0 | Nil | - | Satisfactory | | | | | | |
| 24 | „ | 558 | „ | Tap at BR Stadium SR | 2.0 | Nil | - | Satisfactory | | | | | | |
| 25 | „ | 560 | „ | Tanker filling point at BR stadium SR | 2.0 | Nil | - | Satisfactory | | | | | | |
| 26 | „ | 562 | „ | Tap at LLR naaz centre | 2.0 | Nil | - | Satisfactory | | | | | | |
| 27 | „ | 564 | „ | Tap at HLR Koritrepadu | 2.0 | Nil | - | Satisfactory | | | | | | |
| 28 | „ | 566 | „ | Tap at Sarada colony | 1.5 | Nil | - | Satisfactory | | | | | | |
| 29 | 22.5.14 | 581 | „ | PWS Scheme, Piduguralla Municipality Quarry water | Nil | 1100 | E.coli | Un-Satisfactory | | | | | | Re sampling not necessary |
| 30 | „ | 584 | „ | Sump water from water works | 2.0 | Nil | - | Satisfactory | | | | | | |
| 31 | „ | 586 | „ | Tank filling point at water works | 2.0 | Nil | - | Satisfactory | | | | | | |
| 32 | „ | 589 | „ | Tap near OHSR, neare Municipal office | 1.5 | Nil | -- | Satisfactory | | | | | | |
| 33 | „ | 591 | „ | Tap at Nallabothu Bujji, 19 th ward | 1.0 | Nil | -- | Satisfactory | | | | | | |
| 34 | „ | 593 | „ | Tap at Balarama Krishna 16 th ward | 1.0 | Nil | -- | Satisfactory | | | | | | |
| 35 | „ | 595 | „ | Tap at Yakkala Sai baba, D.No: 8-196, 18 th ward | 1.0 | Nil | -- | Satisfactory | | | | | | |

| | | | | | | | | | | | | | | |
|----|---------|-----|---|-------------------------------------------------------------------------------|-----|------|----------------|-----------------|-------|-------|-------|-------|-------|---------------------------------------------------------------------------|
| 36 | „ | 597 | „ | Tap near Vivekanada School, 15 th ward | 1.0 | Nil | -- | Satisfactory | | | | | | |
| 37 | „ | 599 | „ | Tap at Thota Seshaiyah, 18 th ward | 1.0 | Nil | -- | Satisfactory | | | | | | |
| 38 | 23.5.14 | 621 | „ | PWS Scheme, Macherla Municipality Raw water from Water Works | Nil | 1609 | E.coli | Un-Satisfactory | | | | | | Before chlorination resampling not necessary Re sampling not necessary |
| 39 | „ | 624 | „ | Clarifloculator water | Nil | 1100 | E.coli | Un-Satisfactory | | | | | | |
| 40 | „ | 627 | „ | Water from F.B.No: 1 | Nil | 150 | E.coli | Un-Satisfactory | | | | | | |
| 41 | „ | 630 | „ | Clear water Sump water | 2.0 | Nil | - | Satisfactory | | | | | | |
| 42 | „ | 632 | „ | Tanker filling point at Municipal office | 1.5 | Nil | - | Satisfactory | | | | | | |
| 43 | „ | 638 | „ | Tap at H.No: 12-2-404, 10 th ward | 1.0 | Nil | - | Satisfactory | | | | | | |
| 44 | „ | 641 | „ | Tap at M.Veeraiah house 21 st ward | 1.0 | Nil | - | Satisfactory | | | | | | |
| 45 | „ | 643 | „ | Tap at H.No: 2-251, 21 st ward | 1.0 | Nil | - | Satisfactory | | | | | | |
| 46 | „ | 645 | „ | Tap at 1-329, 22 nd ward | 1.0 | Nil | - | Satisfactory | | | | | | |
| 47 | 24.5.14 | 665 | „ | PWS Scheme, Mpl, Corpn, Vijayawada Raw water at 11 MGD plant | 0.2 | 1100 | E.coli | Un-Satisfactory | | | | | | Before chlorination resampling not necessary Re sampling not necessary |
| 48 | „ | 668 | „ | Clarifloculator water | Nil | 460 | E.coli | Un-Satisfactory | | | | | | |
| 49 | „ | 671 | „ | Filtered water F.B.No: 4 | Nil | 28 | Klebsiella sps | Un-Satisfactory | | | | | | |
| 50 | „ | 674 | „ | Clear water after chlorination | 2.0 | Nil | -- | Satisfactory | | | | | | |
| 51 | „ | 677 | „ | Raw water at 8 MGD plant | 0.1 | 1100 | E.coli | Un-Satisfactory | | | | | | Before chlorination resampling not necessary Re sampling not necessary |
| 52 | „ | 680 | „ | Clarifloculator water | Nil | 460 | E.coli | Un-Satisfactory | | | | | | |
| 53 | „ | 683 | „ | Filtered water F.B.No: 4 | Nil | 21 | Klebsiella sps | Un-Satisfactory | | | | | | |

| | | | | | | | | | | | | | | |
|----|---|-----|---|---------------------------------------------------|-----|------|----------------|-----------------|-------|-------|-------|-------|-------|---------------------------------------------------------------------------|
| 54 | „ | 686 | „ | Clear water after chlorination | 2.0 | Nil | -- | Satisfactory | | | | | | |
| 55 | „ | 689 | „ | Raw water at 16 MGD plant | 0.1 | 1100 | E.coli | Un-Satisfactory | | | | | | Before chlorination resampling not necessary Re sampling not necessary |
| 56 | „ | 692 | „ | Clarifloculator water | Nil | 460 | E.coli | Un-Satisfactory | | | | | | |
| 57 | „ | 695 | „ | Filtered water F.B.No: 4 | Nil | 20 | Klebsiella sps | Un-Satisfactory | | | | | | |
| 58 | „ | 698 | „ | Clear water after chlorination | 2.0 | Nil | -- | Satisfactory | | | | | | |
| 59 | „ | 701 | „ | Raw water at 5 MGD plant | 0.1 | 460 | E.coli | Un-Satisfactory | | | | | | Before chlorination resampling not necessary Re sampling not necessary |
| 60 | „ | 704 | „ | Clarifloculator water | Nil | 21 | E.coli | Un-Satisfactory | | | | | | |
| 61 | „ | 707 | „ | Filtered water F.B.No: 3 | Nil | 7 | Klebsiella sps | Un-Satisfactory | | | | | | |
| 62 | „ | 710 | „ | Clear water after chlorination | 2.0 | Nil | -- | Satisfactory | | | | | | |
| 63 | | 713 | „ | PT at Gandhi Nagar SR | 2.0 | Nil | - | Satisfactory | | | | | | |
| 64 | „ | 715 | „ | PT at D.No: 14-7-9, Namburu Gopalarao St., | 0.5 | Nil | - | Satisfactory | | | | | | |
| 65 | „ | 717 | „ | PT at Tirumala Rao St., | 0.5 | Nil | - | Satisfactory | | | | | | |
| 66 | „ | 719 | „ | PT Opp Ramulavari Temple St., | 1.0 | Nil | -- | Satisfactory | | | | | | |
| 67 | „ | 721 | „ | PT at D.No: 25-9-5, Seethampet | 1.0 | Nil | - | Satisfactory | | | | | | |
| 68 | „ | 723 | „ | PT at D.No: 25-9-8, Seethampet | 1.0 | Nil | - | Satisfactory | | | | | | |
| 69 | „ | 725 | „ | PT at Ramakoti Mandir, Papatla vari St., | 0.5 | Nil | - | Satisfactory | | | | | | |
| 70 | „ | 727 | „ | PT at D.No: 24-1-34, Sambamurthy road, Benarjipet | 0.5 | Nil | -- | Satisfactory | | | | | | |
| 71 | „ | 729 | „ | PT at D.No: 24-1-50, Sambamurthy road, Benarjipet | 0.5 | Nil | - | Satisfactory | | | | | | |
| 72 | „ | 731 | „ | Water from Labbipet 1500 KL SR | 0.5 | Nil | - | Satisfactory | | | | | | |

| | | | | | | | | | | | | | | | |
|----|---------|-----|---|------------------------------------------------------|-----|------|--------|-----------------|--|--|--|--|--|--|---------------------------------------------------------------------------|
| 73 | 29.5.14 | 746 | „ | PWS Scheme, Repalle Municipality Raw water | Nil | 1609 | E.coli | Un-Satisfactory | | | | | | | Before chlorination resampling not necessary Re sampling not necessary |
| 74 | „ | 749 | „ | Clarifloculator water | Nil | 1609 | E.coli | Un-Satisfactory | | | | | | | |
| 75 | „ | 752 | „ | Filtered water F.B.No: 2 | Nil | 210 | E.coli | Un-Satisfactory | | | | | | | |
| 76 | „ | 755 | „ | Clear water sump water | 1.5 | Nil | -- | Satisfactory | | | | | | | |

| Abstract (first sampling) | | Result of Re sampling of unsatisfactory samples |
|------------------------------------------------------------------------------|------------|--------------------------------------------------------------|
| Total No. of samples tested for Residual Chlorine in water samples | 157 | |
| Total No. of samples found Residual Chlorine satisfactory | Nil | |
| Total No. of samples found Residual Chlorine Nil | Nil | |
| Total No. of Samples Collected and tested for Bacteriological quality | 76 | |
| No. of Samples Bacteriologically found satisfactory | 57 | |
| No. of Samples Bacteriologically found unsatisfactory | 19 | |
| Under Process | | 19 nos resampling not necessary Re sampling not necessary |

Senior Analyst
Regional Laboratory
Guntur

Civil Surgeon Bacteriologist
Regional Laboratory
Guntur