

10	7.2.14	5086	B.W.	Government General Hospital Guntur Tap after RO treatment near casualty	Nil	Nil	-	Satisfactory
11	„	5088	„	Cooler water after RO treated at Nursing quarters RO plant	Nil	Nil	-	Satisfactory
12	„	5090	Canal	Sump inlet water from LLR naaz centre	2	Nil	-	Satisfactory
13	„	5092	„	Sump water at Nursing quarters	1.5	Nil	-	Satisfactory
14	„	5094	„	Drinking water stored water in drum in the GGH	Nil	9	Klebsiella sps	Un-Satisfactory	To be Resampled					
15	„	5096	„	Syntex tank water at diet preparation room	Nil	14	Klebsiellasps	Un-Satisfactory						
16	„	5098	„	Cooler water (RO water) at PG hostel	Nil	Nil	-	Satisfactory
17	„	5100	Canal+ B.W	Tap at OHT	Nil	15	Klebsiella sps	Un-Satisfactory	To be Resampled					
18	„	5102	„	Sump water at OHT	Nil	15	Klebsiella sps	Un satisfactory						
19	11.2.14	5112	O.W.	Fairs & Festivals-Kotappakonda Open well water from Yadava Satram	Nil	1609	E.coli	Un-Satisfactory	Resampling not necessary as the samples are direct well waters on 27/2/14 stored water contains RC and satisfactory					
20	„	5115	„	O.W. water from Nayi brahmana colony	Nil	1609	E.coli	Un-Satisfactory						
22	„	5121	B.W.	Tap(B.W. through OHT) Reddy Satram	Nil	4	Klebsiella sps	Un Satisfactory						

23	„	5124	B.W.	Public hand bore left side of Reddy Satram	Nil	93	E.coli	Un-Satisfactory						
24	„	5127	„	Hand bore water at Bhatraju Satram	Nil	1609	E.coli	Un Satisfactory						
25	„	5130	„	Tap(B.W through OHT) Kapu Satram	Nil	28	Klebsiella sps	Un satisfactory						
26	„	5133	„	Hand B.W. Opp PHC	Nil	Nil	-	Satisfactory	
27	„	5136	„	Hand B.W. backside of PHC	Nil	28	E.coli	Un Satisfactory	Resampling not necessary as the samples are direct well waters on 27/2/14 stored water contains RC and satisfactory					
28	„	5139	„	Hand bore back side of Trikoteswara petrol bunk	Nil	1100	E.coli	Un Satisfactory						
29	„	5142	„	PT(RWS) at MP Ele School CPT road	Nil	11	E.coli	Un Satisfactory						
30	„	5145	OW	O.W in Basava Mandiram	Nil	1609	E.coli	Un Satisfactory						
31	„	5148	BW	B.W in Basava Mandiram	Nil	1609	E.coli	Un Satisfactory						
32	„	5151	OW	Open well water in Punnaiah house	Nil	1100	E.coli	Un Satisfactory						
33	„	5154	„	Open well water in Vysya Anna dhana Satram	Nil	93	E.coli	Un Satisfactory						
34	„	5157	„	O.W. water in Padmasaliya Satram	Nil	1609	E.coli	Un Satisfactory						
35	„	5160	B.W.	Hand bore in Jangam devara Anna dhana Satram	Nil	28	Klebsiella sps	Un Satisfactory						
36	„	5163	„	Tap (B.W through syntex tank) Karnabhakthuls Satram	Nil	28	Klebsiella sps	Un Satisfactory						
37	„	5166	OW	O.W wter in Viswabrahmana satram	Nil	1609	E.coli	Un Satisfactory						
38	„	5169	BW	Hand bore water in front of temple steps	Nil	Nil	-	Satisfactory	
39	„	5172	Canal	Cheruvu wter at temple scheme	Nil	1609	E.coli	Un Satisfactory	Resampling not necessary as the samples are under treatment					

40	„	5175	OW	Open well in cheruvu temple scheme	Nil	1609	E.coli	Un Satisfactory	resampling not necessary as the samples are under treatment					
41	14.2.14	5190	Canal	PWS Schem Tadepalli	0.5	Nil	-	Satisfactory	
				PT at Gandhi park SR										
42	„	5193	„	PT at Burripalem road	0.5	Nil	-	Satisfactory	
43	„	5195	„	PT near D.No: 1-1-64, Burripalem road	0.5	Nil	-	Satisfactory	
44	„	5197	„	PT at D.No: 1-10-11, Chennam vari Veedhi	0.2	Nil	-	Satisfactory	
45	„	5199	„	PT at D.No: 1-26-2, Kukkalavariveedhi	0.2	Nil	-	satisfactory	
46	„	5201	„	PT at D.N: 1-27-39, Tankasala vari veedhi	0.2	Nil	-	Satisfactory	
47	„	5203	„	PT at old RTC Depot line	0.1	Nil	-	Satisfactory	
48	„	5205	„	PT in front of Community hall	Traces	Nil	-	Satisfactory	
49	„	5208	„	PT at Hudco colony	Nil	Nil	-	Satisfactory	
50	21.2.14	5276	„	PWS Scheme	Nil	1609	E.coli	Un Satisfactory	Resampling not necessary as the samples are under treatment					
				Raw water from water works										
51	„	5279	„	Clarifloculator water	Nil	460	E.coli	Un Satisfactory						
52	„	5282	„	Filter bed No:1 water	Nil	93	Klebsiella sps	Un						
53	„	5285	„	Clear water sump water	1.5	Nil	-	Satisfactory	
54	„	5287	„	PT at Pandaripuram	1	Nil	-	Satisfactory	
55	„	5291	„	SR water at Gandhi Park	1	Nil	-	Satisfactory	
56	„	5293	„	Tap near rice mill	Nil	4	Klebsiella sps	Un Satisfactory	To be resampling					
57	„	5295	„	PT at fire station	Nil	4	Klebsiella ss	Un Satisfactory						
58	25.2.14	5344	„	PWS Scheme Guntur	2	Nil	-	Satisfactory	
				Tap at PH office SR										
59	„	5346	„	Tap at Bose Bomma centre	1.5	Nil	-	Satisfactory	
60	„	5348	„	PT at Gundaraopet	1	Nil	-	Satisfactory	

61	„	5350	„	PT at Srinivasarao pet SR	1.5	Nil	-	Satisfactory	
62	„	5352	„	PT at Nallacheruvu SR	2	Nil	-	Satisfactory	
63	„	5354	„	Tap at LLR Naaz centre	2	nil	-	Satisfactory	
64	„	5356	„	Tap at H.No: 13-2-13,	1	Nil	-	satisfactory	
65	27.2.14	5387	B.W.	Fairs & Festivals-Govada	Nil	Nil	-	satisfactory	
				Tank water at Mandal Praja Parishat primary school										
66	„	5389	„	Tank water in the premises of Govada temple	Nil	Nil	-	satisfactory	
67	„	5398	„	Fairs & Festivals-Quarry, Chebrolu (Md)- Bore well	Nil	Nil	-	satisfactory	
68	„	5396	„	Wisdom packed water-200	Nil	Nil	-	Satisfactory	
69	„	5399	Canal	Fairs & Festivals-Quarry, Amaravathi	2	Nil	-	satisfactory	
				Raws water from filter bed in temple										
70	„	5402	„	V natch water	2	Nil	-	Satisfactory	
71	„	5405	„	Clear water sump water	2	Nil	-	Satisfactory	
72	„	5408	„	Drinking water taps in temple premises	2	Nil	-	Satisfactory	
73	„	5411	„	Tap water in Dattatreya	2	Nil	-	Satisfactory	
74	„	5414	„	Tap water in front of Laddu reparation room	2	Nil	-	Satisfactory	
75	„	5417	„	Thanmai min packed water	Nil	Nil	-	Satisfactory	
76	„	5437	Canal	Fairs festivals Kotappakonda	2	Nil	-	Satisfactory	
				PT near OHSR										

77	„	5440	B.W.	Minerva water Sachet	Nil	Nil	-	Satisfactory	
78	„	5443	„	Thanmai water bottle 500	Nil	Nil	-	Satisfactory	
79	„	5446	O.W.	Stored water at Redla Satram	2	Nil	-	Satisfactory	
80	„	5449	„	Stored water at Kapu	2	Nil	-	Satisfactory	
81	„	5452	„	Stored water at Rajaka	2	Nil	-	Satisfactory	
82	„	5455	„	Stored water at Brahmana	2	Nil	-	Satisfactory	
83	„	5458	„	Stored water at Kakatiya	2	Nil	-	Satisfactory	
84	„	5461	„	Stored water at Yadava	2	Nil	-	Satisfactory	
85	„	5464	„	Stored water at Vaddera	2	Nil	-	Satisfactory	
86	„	5467	„	Stored water at Viswa	2	Nil	-	Satisfactory	
87	„	5469	„	Stored water at Erukala	2	Nil	-	Satisfactory	
88	„	5471	„	Stored water at BAtrajula	2	Nil	-	Satisfactory	
89	„	5473	„	Stored water at Basava mandiram	2	Nil	-	Satisfactory	
90	„	5475	„	Stored water at Vysya satram	2	Nil	-	Satisfactory	
91	„	5477	„	Stored water at Padmasalisatram	2	Nil	-	Satisfactory	
92	„	5479	„	Stored water at Jangam devara satram	2	Nil	-	Satisfactory	
93	„	5481	„	PT back side of temple	1	Nil	-	Satisfactory	
94	„	5483	„	PT left side of temple	1	Nil	-	Satisfactory	
95	„	5485	„	PT in temple steps	1	Nil	-	Satisfactory	

Abstract (first sampling)		Result of Re sampling of unsatisfactory samples
Total No. of samples tested for Residual Chlorine in water samples	193
Total No. of samples found	166
Total No. of samples found	27
Total No. of Samples Collected	95
No. of Samples Bacteriologically found	64	(25 are under treatment & well water samples)
	31	
No. of Samples Bacteriologically found unsatisfactory		
Under Process		6

Civil Surgeon Bacteriologist
Regional Laboratory
Guntur