

12	„	5574	„	PT in front of D.No:28-9-159, Venkateswarapuram	1.5	Nil	--	Satisfactory
13	„	5576	„	Haranadaha puram ELSR water	2.0	Nil	--	Satisfactory
14	„	5580	,	PT at Saraswathi Nagar Opp. Indian gas road	1.0	Nil	--	Satisfactory
15	„	5584	„	Tap at Podalakur road	2.0	Nil	--	Satisfactory
16	„	5586	„	PT at Rajagari Veedhi, Mulapet	1.0	Nil	-	Satisfactory
17	„	5592	,	PT in front of Gandhi Nagar SR	1.5	Nil	--	Satisfactory	
18	„	5594	,	Jakir Hussain Nagar GLSR water	1.5	Nil	--	Satisfactory	
19	„	5596	„	Akuthota Harijanawada pumping station water	2.0	Nil	--	Satisfactory	
20	„	5599	„	S.S. Tank water	Nil	1609	E.coli	Un-Satisfactory	Re sampling is not necessary as the sample is under process
21	„	5602	„	Clarifloculator water	Nil	240	E.coli	Un-Satisfactory	
22	„	5605	„	Water from Filter Bed No: 2	Nil	75	Klebsiella sps	Un-Satisfactory	
23	„	5608	„	Clear water sump water	2.0	Nil	-	Satisfactory	
24	„	5611	,	PT near OHSR Nava Lock Thota	Nil	210	Klebsiella sps	Un-Satisfactory	To be Resample
25	„	5614	„	PT at Narayana Reddy pet kotha Cabnal	Nil	28	Klebsiella sps	Un-Satisfactory	
26	„	5617	„	PT at Pedda Cherukuru Reservoir Revenue office	Nil	20	Klebsiella sps	Un-Satisfactory	
27	„	5620	B.W.	Bore well water at Allipuram P.G.K. colony	Nil	120	Klebsiella sps	Un-Satisfactory	Re sampling is not necessary as the sample is under process

28	„	5623	„	Chinta reddy palem OHSR water	Nil	15	Klebsiella sps	Un-Satisfactory	To be Resample
29	„	5626	„	PT near Gudipalli padu OHSR	Nil	28	Klebsiella sps	Un-Satisfactory	
30	4.3.14	5639	Penna river	PWS Scheme Kavali Municipality Raw water from 5.77 MLD plant	Nil	1609	E.coli	Un-Satisfactory	Re sampling is not necessary as the sample is under process
31	„	5642	„	Clarifloculator water	Nil	1100	E.coli	Un-Satisfactory	
32	„	5645	„	Water from Filter Bed No: 1	Nil	75	Klebsiella sps	Un-Satisfactory	
33	„	5648	„	Clear water sump water	2.0	Nil	--	Satisfactory	
34	„	5651	„	Tap at IDSMT area OHSR	1.5	Nil	--	Satisfactory	
35	„	5654	„	Ambedkar Nagar Open well water	2.0	Nil	--	Satisfactory	
36	„	5656	„	Tap at D.No: 12-21-18/F Billa Vari Veedhi	1.0	Nil	--	Satisfactory	
37	„	5664	„	Open well water at Agraharam	1.5	Nil	--	Satisfactory	
38	,	5666	„	Tap at D.No: 10-15-29, Jaya Usha line	1.0	Nil	-	Satisfactory	
39	„	5674	„	Maddurupadu open well water	1.5	Nil	--	Satisfactory	
40	„	5676	„	Tap at H.No: 6-13-5/A, Komatilavari veedhi	1.0	Nil	--	Satisfactory	

41	26.3.14	5817	Krishna Canal	PWS Scheme Narasaraopet Raw water from Water works Santhi Nagar	Nil	1609	E.coli	Un-Satisfactory	Re sampling is not necessary as the sample is under process
42	„	5820	„	Clarifloculator water	Nil	1100	E.coli	Un-Satisfactory	
43	„	5823	„	Water from Filter Bed No: 2	Nil	75	Klebsiella sps	Un-Satisfactory	
44	„	5826	„	Clear water sump water	2.0	Nil	--	Satisfactory
45	„	5829	„	Tap at TB SR	2.0	Nil	--	Satisfactory
46	„	5831	„	PT at Swamy school Prakash Nagar	1.5	Nil	--	Satisfactory
47	„	5833	„	PT at Rekshaw Centre Prakash Nagar	1.0	Nil	--	Satisfactory
48	„	5835	„	HT at Sree Krishna mess 60 feet road	1.0	Nil	--	Satisfactory
49	„	5837	„	Tap at Srinivasaraopet SR	1.5	Nil	-	Satisfactory
50	„	5839	„	HT Guntur Mallamma centre	1.0	Nil	--	Satisfactory
51	„	5841	„	PT at Ranga bomma Gunturroad	1.0	Nil	--	Satisfactory
52	„	5843	„	Tap at Anjaneya swamytempleBarampet	1.0	Nil	-	Satisfactory
53	„	5845	„	PT at PH office SR	2.0	Nil	-	Satisfactory

54	„	5847	„	HT at D.No:3-2-6/153, Three ways centre	1.0	Nil	-	Satisfactory
55	„	5849	„	HT at D.No:3-23-2/1, Pedda cheruvu Bypass	1.0	Nil	-	Satisfactory
56	„	5851	„	PT at NGO colony SR	2.0	Nil	-	Satisfactory
57	„	5853	„	PT Opp.D.No:11-15-42/2 Ramireddy Pet	0.5	Nil	-	Satisfactory
58	29.3.14	5909	Krishna canal	PWS Scheme Municipal Corporation Guntur Tap at Nalla Cheruvu SR	2.0	Nil	-	Satisfactory
59	„	5912	„	TapatAT Agraharam 3 rd line	1.5	Nil	-	Satisfactory
60	„	5914	„	Tap at Bose Bomma Centre	1.0	Nil	-	Satisfactory
61	„	5916	„	PT at Kannavarithoata	1.0	Nil	-	Satisfactory
62	„	5918	„	Sump water at DM&HO office	0.5	Nil	-	Satisfactory
63	„	5920	„	Tap at PH office SR	1.0	Nil	-	Satisfactory
64	„	5922	„	Tap at Park Koritepadu	1.0	Nil	-	Satisfactory
65	„	5924	„	Tap at Sivalayam, Amaravathi road	1.0	Nil	-	Satisfactory

Abstract (first sampling)		Result of Re sampling of unsatisfactory samples
Total No. of samples tested for Residual Chlorine in water samples	155	
Total No. of samples found Residual Chlorine satisfactory	149	
Total No. of samples found Residual Chlorine Nil	06	
Total No. of Samples Collected and tested for Bacteriological quality	65	
No. of Samples Bacteriologically found satisfactory	49	
No. of Samples Bacteriologically found unsatisfactory	16 (11 are under treatment & well water samples)	5 sample are to be resampling
Under Process		--

Abstract

No.of samples found un-Satisfactory: 05